

## ADDENDUM 1

Request for Quotes FY13-0327Air-Cooled Water Chiller Replacement

Addendum No.:   1   (herein referred to as "Addendum")

This Addendum revises the above-described procurement, and is hereby incorporated and made a part of the above-described procurement as if the Addendum had been included in the original procurement documents. Addendum posted on website at [www.orangeburgcounty.org](http://www.orangeburgcounty.org) – Purchasing/Bids - Solicitations – Questions/Answers

**Q1. Can you provide us with a start/completion date?**

A1. Start/completion date should be addressed in your quotation

**Q2. What type of chiller that you all would like to consider: ex: Trane, Carrier, York, McQuay, etc.**

A2. There is a Trane unit in place. We do not have a preference.

**Q3. Are site visits still available?**

A3. Yes, we would like you to look at the existing unit located behind our Administrative Bldg. at 1437 Amelia Street., Orangeburg, S. C. 29115

Q4. Is there a time frame for the chiller change out? This will affect pricing

A4. We would hope to change out the unit as soon as possible upon making a decision on the quote. You should address the time frame in your quote, time it would take you to get a unit and change it out.

**Q5. Please advise of a desired day and time and we will be available.**

A5. You can see it any time during the day between 8:30 and 5:00 p.m. There is no gate or fence and you do not need an appointment of escort

**Q6. Do you have a model and serial number for the chiller that is there now?**

A6. The nameplate info was removed, we don't have that info.

**Q7. Does the chiller have to be scroll compressors or would a screw compressor be acceptable.**

A7. Scroll compressors would be preferred.

**Q8. Does the chiller have to be a Trane?**

A8. No it does not have to be Trane.

**Q9. Will the bids be opened on March 27th @ 11:00 to the public?**

A9. No, this is a Request for Quote. Only names of responding vendors will be read aloud.

**Q10. Does the existing disconnect need to be replaced, and if so does the new one have to be attached to the chiller and not to the existing brackets?**

A10. A new disconnect is required and should be located where the onl one is located and not inside the chiller compartment.

Vendor shall submit a completed Addendum Acknowledgement form with its submission.  
**Vendor may be disqualified from this procurement unless vendor submits a completed Addendum Acknowledgement form referring to this Addendum with vendor's proposal.**